# Kahn® Solid Carved

Carved granite, warning 23640.1 / directional 23640.2

WET PENDULUM CLASSIFICATION

## P5

**AS 4586:2013**

### TEST RESULT

| | |
|---|---|
| **Classification** | P5 (wet-pendulum class, AS 4586) |
| **Test method** | Wet pendulum, AS 4586:2013, Appendix A |
| **Slider rubber** | Slider 55 |
| **Test specimens** | 5 specimens (sampling by client) |
| **Test date** | 12 December 2025 |

### INDEPENDENT VERIFICATION

| | |
|---|---|
| **Testing laboratory** | ATTAR, Advanced Technology Testing and Research |
| **Accreditation** | NATA accredited to ISO/IEC 17025 · Accreditation No. 2735 |
| **Report number** | 23640.1 |

**Independent NATA accredited test result.** Korb slip resistance testing is conducted by ATTAR (NATA accredited, ISO/IEC 17025). This summary states the classification for this product; the full NATA test report is available on request. Results apply to the specimens tested. The effect of service conditions, maintenance and wear on slip resistance should be considered in selection, and slip resistance for stairways and pedestrian surfaces should be appropriate to the application per AS 1428.1 and the NCC.

**National (Head Office)**
T 1300 00 KORB (5672)
E info@korb.au

**Melbourne**
17 Anderson Road,
Thornbury VIC 3071
T +61 3 8506 0106
E melbourne@korb.au

**Adelaide**
71 Maria Street, Thebarton
SA 5031
T +61 8 7081 9811
E adelaide@korb.au

**Perth**
U4/4 McNeece Place,
O'Connor WA 6163
T +61 8 6119 3795
E perth@korb.au

Korb Pty Ltd
**ABN 26 159 533 454**